

*Honeywell Aerospace*  
*Hereby Appoints*  
**Intermountain Turbine Services, Inc.**

Of


*West Landon, Utah*

*As An*

***Authorized Service Center***

Meeting standards required to perform service and repair up to, and including,  
Overhaul capability on the following LTS-101 Turboshaft engine models:  
600A-1A, 600-A-2, 600A-3/3A, 650C-3/3A, 650B-1, 700A-1A/3A, 700-D-2, 750B-1, and 750C-1

**Signed into Agreement and Remains in effect through 31 December 2016  
unless cancelled, suspended, or revoked.**



**Honeywell**

---

**Richard Leask**  
**Sr. Manager Licensing COE**