

Goodrich Pump and Engine Controls
Charter Oak Blvd.
West Hartford CT, 06133

May 1, 2012

Goodrich Pump and Engine Controls, Charter Oak Blvd. West Hartford CT 06133 after performing the necessary training at Intermountain Turbine Services, Inc. and after auditing the Intermountain Quality system which was found acceptable fully authorizes Intermountain Turbine Services, Inc. 270 South 1060 West Lindon UT, to inspect, repair and overhaul Goodrich Model MFP 261 Main Fuel Pumps, MFP 265 Main Fuel Pumps and HPF1 Filters.



Richard Urban
Sr. Staff Engineer
Goodrich